

Commercial Register No.: FN 217491s Regional Court Wels UID-No.: ATU53018309 DVR: 0381080

OBERBANK, BIN 15130 Account 283-0701/00 IBAN AT70 1513 0002 8307 0100 SWIFT: OBKLAT2L

May 11th, 2021

Technical statement

Dear Kitatomi San,

We have received the pictures below with your email sent on Monday May 10th, 2021. On the pictures 1 and 2 it is evident that the exhaust is mounted using a flexible mount – see highlighted sections - which allows movement in multiple directions.



Picture 1

Picture 2



The type of installation seen on the pictures is causing an infringement with the Global Technical Regulations 2021 (see paragraph below). This installation is illegal to use according to the regulations.

Section 6.17, 125 MICRO MAX

The Exhaust must be installed firmly to the chassis using a rigid mount/s. The Exhaust must be mounted to the rigid mount/s using 2 ROTAX silent blocks. (part 660920 and or 260657 allowed). The deflection of the 2 silent blocks is the only Exhaust movement allowed. The Exhaust must be mounted in a neutral position with no stress on the 2 silent blocks.

Yours sincerely,

i.A. Alexander Wand/ / After Sales Service

BRP-Rotax GmbH & Co KG