

IMPROVED IMPELLER FIXATION 125 MAX, 125 MAX DD2

2012-09-26

Dear Distributor,

We kindly inform you about the introduction of the new, improved dowel for the water pump shaft impeller for all 125 MAX and 125 MAX DD2 engines.



Advantages:

The new dowel provides higher pre-tension in combination with an improved design compared to the previous dowel. The new design reduces the risk that the dowel gets loose during engine operation.

Part numbers and availability:

The introduction into serial production (engines and water pump shaft assy.) will be with running change.

For spare parts the dowel will be available as of now. Part no. 229200

We strongly recommend retrofitting water pump shaft assemblies on stock to prevent loose water pump impellers. (engine will overheat!)